

Building address: Skrindu iela 1
 Building type: Non-residential
 Year of construction: < 1960
 Date: 5-06-2024
 Assessor's name: Edgars Augustiņš



Total SRI Score: 33 %
SRI Class: F


IMPACT SCORES

Energy Efficiency:	56.14%
Energy Flexibility and Storage:	13.56%
Comfort:	66.67%
Convenience:	33.33%
Health, well-being and accessibility:	45%
Maintenance and fault prediction:	27.86%
Information to occupants:	28.7%



DOMAIN SCORES

Heating:	43.43%
Domestic hot water:	69.88%
Cooling:	0%
Ventilation:	59.09%
Lighting:	29.27%
Dynamic building envelope:	0%
Electricity:	21.69%
Electric vehicle charging:	0%
Monitoring and control:	16.16%



DETAILED SCORES

Heating:	80 %	0 %	66.7 %	62.5 %	66.7 %	50 %	66.7 %
Domestic hot water:	100 %	66.7 %	0 %	66.7 %	0 %	50 %	66.7 %
Cooling:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Ventilation:	45.5 %	0 %	80 %	87.5 %	77.8 %	50 %	33.3 %
Lighting:	33.3 %	0 %	40 %	40 %	0 %	0 %	0 %
Dynamic building envelope:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Electricity:	50 %	0 %	0 %	0 %	0 %	25 %	66.7 %
Electric vehicle charging:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Monitoring and control:	25 %	11.1 %	66.7 %	11.8 %	0 %	9.1 %	0 %

Energy Efficiency:	Energy Flexibility and Storage:	Comfort:	Convenience:	Health, well-being and accessibility:	Maintenance and fault prediction:	Information to occupants:
80 %	0 %	66.7 %	62.5 %	66.7 %	50 %	66.7 %
100 %	66.7 %	0 %	66.7 %	0 %	50 %	66.7 %
0 %	0 %	0 %	0 %	0 %	0 %	0 %
45.5 %	0 %	80 %	87.5 %	77.8 %	50 %	33.3 %
33.3 %	0 %	40 %	40 %	0 %	0 %	0 %
0 %	0 %	0 %	0 %	0 %	0 %	0 %
50 %	0 %	0 %	0 %	0 %	25 %	66.7 %
0 %	0 %	0 %	0 %	0 %	0 %	0 %
25 %	11.1 %	66.7 %	11.8 %	0 %	9.1 %	0 %

AGGREGATED SCORES

1:	42%
2:	43.43%
3:	13.56%