

Building address: Dammes Iela 20  
 Building type: Non-residential  
 Year of construction: 1960-1990  
 Date: 5-06-2024  
 Assessor's name: Edgars Augustiņš



**Total SRI Score: 15.9 %**  
**SRI Class: G**


### IMPACT SCORES

Energy Efficiency:	41.97%
Energy Flexibility and Storage:	3.95%
Comfort:	16.9%
Convenience:	11.11%
Health, well-being and accessibility:	5.88%
Maintenance and fault prediction:	14.98%
Information to occupants:	27.56%



### DOMAIN SCORES

Heating:	31.31%
Domestic hot water:	46.99%
Cooling:	0%
Ventilation:	0%
Lighting:	0%
Dynamic building envelope:	0%
Electricity:	13.25%
Electric vehicle charging:	0%
Monitoring and control:	5.05%



### DETAILED SCORES

Heating:	70 %	0 %	50 %	37.5 %	33.3 %	25 %	66.7 %
Domestic hot water:	66.7 %	33.3 %	0 %	33.3 %	0 %	50 %	66.7 %
Cooling:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Ventilation:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Lighting:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Dynamic building envelope:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Electricity:	33.3 %	0 %	0 %	0 %	0 %	0 %	66.7 %
Electric vehicle charging:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Monitoring and control:	12.5 %	0 %	0 %	5.9 %	0 %	9.1 %	11.1 %

	Energy Efficiency:	Energy Flexibility and Storage:	Comfort:	Convenience:	Health, well-being and accessibility:	Maintenance and fault prediction:	Information to occupants:
Heating:	70 %	0 %	50 %	37.5 %	33.3 %	25 %	66.7 %
Domestic hot water:	66.7 %	33.3 %	0 %	33.3 %	0 %	50 %	66.7 %
Cooling:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Ventilation:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Lighting:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Dynamic building envelope:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Electricity:	33.3 %	0 %	0 %	0 %	0 %	0 %	66.7 %
Electric vehicle charging:	0 %	0 %	0 %	0 %	0 %	0 %	0 %
Monitoring and control:	12.5 %	0 %	0 %	5.9 %	0 %	9.1 %	11.1 %

### AGGREGATED SCORES

1:	28.48%
2:	15.36%
3:	3.95%